





Wood NC Clear Coat

Instruction

First clean the surface from grease, rust and dust. Add NC thinner to reach the proper viscosity, and then apply with spray gun.

	Spray Viscosity 20-22 Cup No.4 NC Thinner: 25% weight of the paint
	1.3-1.4 mm 4 bar
	Drying Time: 100 min at 20°C
	36 months