





NC Primer

Instruction

First clean the surface from grease, rust and dust. Add NC thinner to reach the proper viscosity, and then apply with spray gun.

	Spray Viscosity 20-22 Cup No.4 NC Thinner: 25% weight of the primer
	1.3-1.4 mm 4 bar
	10 min / 20°C
	Drying Time: 100 min at 20°C
	P 240
	Further Treatment: Top Coat
	36 months